



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip for Malfunction Indicator Lamp (MIL) On, DTC P0503 Only Set with No Other Symptoms

Models: 2015 Chevrolet Corvette
Equipped with Manual Transmission (MEK or MEL)

Attention: This PI also applies to any of the above models that may be Export vehicles.

Condition/Concern

Some customers may comment on a Malfunction Indicator Lamp (MIL) on. During diagnosis you may notice that the Engine Control Module (ECM) has stored a P0503 DTC. No other symptoms will be present.

This may be caused the vehicle software interpreting a vehicle speed sensor signal change following a wheel spin event as a vehicle speed sensor fault.

Recommendation/Instructions

Important: Do **NOT** replace the vehicle speed sensor for this issue.

Engineering is aware of this condition and working on a resolution. Once a solution becomes available, this PI will be updated. In the meantime, the technician can clear the code.

Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION