



Service Bulletin

PRELIMINARY INFORMATION

Subject: Vehicle Rides Rough and/or Fluid Leak from Rear of Vehicle Near Tire

Models: 2015 Chevrolet SS

Condition/Concern



Some customers may comment that the vehicle rides rough in the rear and/or that the vehicle is leaking from the rear shock absorber location. This may be caused by a defective seal within the rear shock absorber, leaving particles which will not allow the absorber to work as intended.

Recommendation/Instructions

If you encounter a vehicle with the above concern, visually inspect for a leaking rear absorber.

Replace the affected shock absorber. Refer to Shock Absorber Replacement in SI.

Parts Information

Part Number	Description
22761221	LINK, RR STAB SHF
11516078 (Qty 3)	NUT, R/AXL LWR CONT ARM
92269317	ABSORBER ASM-RR SHK

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8044750	Shock Absorber Replacement	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION