



Bulletin No.: PI1525A

Date: Aug-2015

Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tips for Airbag Readiness Light On, DTC B101D SYM 00 and C0186, C0196 and/or C0287 Set

Models: 2014-2015 Buick Regal
2015 Chevrolet Malibu Built After June 30, 2014
2015 Chevrolet Sonic

Attention: This PI also applies to any of the above models that may be Export vehicles.

This PI has been revised to direct dealers to use published diagnostics in SI. Please discard PI1525.

If you encounter a vehicle with this condition, refer to published diagnostics in SI.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION