



Service Bulletin

PRELIMINARY INFORMATION

Subject: Information Only - Radio Antenna Amplifier Found In Vehicle Trunk Bag

Models: 2015 Chevrolet Impala

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Upon performing a Pre-Delivery Inspection (PDI) a Technician might notice that there is a Radio Antenna Amplifier in the Trunk Bag.

Recommendation/Instructions

No repairs are to be performed, the Radio Antenna Module was correctly installed during the build process but on certain vehicles there was also a Radio Antenna Amplifier mistakenly put into the Trunk Bag. There will not be a request to have these parts returned. As such, please discard the additional amplifier.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION