



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Diagnostic Tip: Performance Data Recorder SD Card Not Recognized

**Models:** 2015 Chevrolet Corvette  
With RPO UQT

### Condition/Concern

Customer may comment that the vehicle does not recognize the SD card when inserted into the hub in the glove box. There may or may not be an error message displayed on the radio display.

### Recommendation/Instructions

The SD card needs to be formatted to FAT32 and also have a class 10 designation in order to be compatible with the system.

If the vehicle is intermittently losing connection with the SD card, there may be an issue with the connector at the back of the SD card hub, or the harness being stressed causing a poor connection at the hub.

**Note:** Although the system is capable of reading larger SD cards, the system performance is optimized if a 32gb or less SD card is used.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION