



Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Lamp On With DTC P151E

Models: 2015 Chevrolet Colorado
2015 GMC Canyon
Equipped with 3.6L Engine (RPO LFX)

This PI was superseded to update Part and Warranty Information. Please discard PIT5364.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The SES lamp may be on with both DTC P151E and P069E stored.

Recommendation/Instructions

Important: This concern does NOT involve the DTC P059F. Do NOT replace parts for DTC P059F as this DTC is often an indicator of obstruction in the shutter such as road debris, ice, or snow.

Note: An easier "Service Fix" is still being validated. This PI will be updated again once the Service Fix becomes available.

Replace the Active Grille Air Shutter assembly for DTC P151E. Revisions to the Shutter will resolve this concern.

Parts Information

Part Number	Description	Qty
23347863	SHUTTER ASM,FRT BPR	1

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
1421130	Front Bumper Lower Shutter Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION