



Service Bulletin

PRELIMINARY INFORMATION

Subject: 8L90 Repeat Harsh Shift After Latest TCM Calibration And Relearning The Shift Adapts

Models: 2015 Cadillac Escalade, Escalade ESV
2015 Chevrolet Corvette, Silverado
2015 GMC Sierra, Yukon, Yukon XL
Equipped with 8L90 Automatic Transmission (RPO M5U)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment on a repeat harsh shift, slip or flare concern after performing the service fast learn and the drive learn procedures listed in the latest version of bulletin 14-07-30-001.

Recommendation/Instructions

Please verify the latest TCM calibration has been installed.

Confirm the transmission service fast learn and drive learn procedures listed in the latest version of bulletin 14-07-30-001 were performed

If the vehicle continues to have shift concerns with the latest calibration installed and relearning the shift adapts contact TAC

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION