



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Intermittently Radio Display Has Flickering Or Rolling Image

**Models:** 2014 Chevrolet Corvette Stingray

*This PI was superseded to update Part Information. Please discard PIC5934B*

### Condition/Concern

On rare occasions, a customer or dealer may comment that the radio display is blinking, flickering, rolling, or scrolling.

Typical comments are that it looks like an old TV with a rolling image and that raising or lowering the display may make the concern come and go

### Recommendation/Instructions

If this concern is encountered, replace the radio display to address this concern.

### Parts Information

Refer to Group 09.768 of the electronic parts catalog for the latest radio display part number that is designed to address this concern.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
3430990	Driver Information Display Replacement	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION