



Service Bulletin

PRELIMINARY INFORMATION

Subject: P0496 After Performing Strategy Based Diagnostics

Models: 2013-2015 Chevrolet Trax and Buick Encore
Equipped with the 1.4L Turbocharged LUJ LUV engines

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Vehicle continues to set DTC P0496 after you have completed Strategy Based Diagnostics

Recommendation/Instructions

Contact GM TAC if you have a 2013-2015 Chevrolet Trax or Buick Encore that continues to set DTC P0496 after you have completed Strategy Based Diagnostics

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION