



Service Bulletin

PRELIMINARY INFORMATION

Subject: Turbo Upgrade Kit Not Available

Models: 2010 Pontiac Solstice GXP
2010 Saturn Sky Redline
With 2.0L Engine RPO LNF

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may inquire as to the availability of the Stage-1 turbo upgrade kit for the 2010 Pontiac Solstice GXP and or 2010 Saturn Sky Redline

Recommendation/Instructions

Due to the Pontiac / Saturn brand closures and limited production, a decision was made not to support these vehicles with the required calibration for the kit. There will be no future review of this situation.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION