



Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Lamp P06DD Set

Models: 2014-2015 Chevrolet Corvette
2014-2015 Chevrolet Silverado 1500
2014-2015 GMC Sierra 1500
Built with RPO's 4.3L 5.3L 6.2L L83 L86 LT1 LT4 LV3

This PI was superseded to update Recommendation/Instructions. Please discard PIP5141G.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A vehicle may set a P06DD code with no drivability concerns

Recommendation/Instructions

This PI has been updated to advise Dealers to follow SI document ID: 3269210.

Thank you

This PI will be deleted in 30 days

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION