



Service Bulletin

PRELIMINARY INFORMATION

Subject: TAC Part Restriction Ended Hybrid Powertrain Control Module 2 (HPCM 2) Part Restriction

Models: 2011-2015 Chevrolet Volt
2014-2015 Cadillac ELR

This PI was superseded to update Part Restriction. Please discard PIC5380G.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The Part Restriction for the Hybrid Powertrain Control Module 2, also known as the HPCM2 part numbers 22994053 and 22985723 has ended. Thank you for your assistance in collecting data

Recommendation/Instructions

These part number can now be ordered directly through your parts department without TAC authorization

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION