



Service Bulletin

PRELIMINARY INFORMATION

Subject: Heated or Cooled Seat Switches or HVAC Buttons Flashing

Models: 2014-2015 Chevrolet Corvette Stingray

Condition/Concern

Some customers may comment that the heated and cooled seat switches or HVAC control buttons will flash or flicker at times but all other HVAC functions still operate normally as this is happening.

Recommendation/Instructions

Please do not replace the button assembly/ICS (Integrated Center Stack) for this concern. Please inspect connections at the 20 way connector between the ICS and the display and if no concerns are found replace the radio display. Please refer to the latest version of PIC6095 for proper part identification

Parts Information

Refer to Group 09.768 of the electronic parts catalog for the latest radio display part number that is designed to address this concern.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
3430990	Driver Information Display Replacement	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION