



Service Bulletin

PRELIMINARY INFORMATION

Subject: Fuel Tank Hard to Fill

Models: 2014-2015 Chevrolet Equinox
2014-2015 GMC Terrain
Equipped With a V6 Engine Only

This PI was superseded to update Model Years, Recommendation/Instructions, Parts and Warranty Information. Please discard PIP5297

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may have difficulty filling the fuel tank and / or experience fuel spit-back when fueling.

The customer may also note the fuel gauge takes an extended period of time to reach the full mark after completely filling the tank.

Recommendation/Instructions

If SI diagnostics does not lead to a repair perform the following:

Replace the fuel tank assembly and fuel pump assembly O-ring seals.

Parts Information

Part Number	Description	Qty
23350611	Fuel Tank	1
22682111	Primary fuel pump o-ring seal	1
15776433	Secondary fuel pump o-ring seal	1

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4029250	Fuel Tank Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that

your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION