



Service Bulletin

PRELIMINARY INFORMATION

Subject: Sunroof Contacts #2 Roof Bow

Models: 2015 Cadillac ATS Sedan

Condition/Concern

A customer may comment that when opening the sunroof the glass contacts the number 2 roof bow. The contact may be enough to produce scratches on the glass.

Recommendation/Instructions

Perform the Sunroof Window Height and Opening Fit Adjustment procedure in Service Information. If the glass adjustment is correct, contact Technical Assistance for further information.

Warranty Information

For vehicles repaired under warranty use:

| Labor Operation | Description | Labor Time |
|-----------------|--|------------------------------------|
| 6040362 | Sunroof Window Height and Opening Fit Adjustment | Use Published Labor Operation Time |

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION