



Service Bulletin

PRELIMINARY INFORMATION

Subject: P0300 Misfire At Speeds Of 70 MPH – 3rd Gear – 3500 – 4500 RPM'S

Models: 2009-2015 Cadillac CTS-V

2012-2015 Chevrolet Camaro

Built with 6.2L LSA supercharged engine (Only)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A vehicle has a concern of a misfire event that usually occur at speeds of 70 mph, 3rd Gear, 3500 – 4500 rpm's

Recommendation/Instructions

Advise customer/dealer to refer to TopTierFuel.com for availability in their respective area and fill with 91 or higher octane level fuel.

Please refer bulletin 05-06-04-022M TOP TIER Detergent Gasoline Information and Available Brands with the customer

Also if tires and or wheels have been changed be sure the tires and wheels are the correct size for the vehicle. (same diameter and tread size)

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION