



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - EBCM DTC C025E

Models: 2014 - 2015 Chevrolet Malibu
2016 Chevrolet Malibu Limited

This PI was superseded to update the Model Years. Please discard PIC5938.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

When performing a DTC check using a scan tool, a Technician may find the Electronic Brake Control Module (EBCM) has a DTC C025E SYM5A (vacuum sensor signal is not plausible) set in history. If the DTC is cleared, they may find the DTC sets again and immediately goes to history during the next ignition cycle
NOTE: No messages or MIL will display on the IPC.

Recommendation/Instructions

Important: Do NOT replace any components for this condition.

This is a characteristic of normal operation.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION