



Service Bulletin

PRELIMINARY INFORMATION

Subject: Burning Odor on Volts When Operating in Extended Range, Hold, or Mountain Modes

Models: 2016 Chevrolet Volt

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Engine Cover Foam not installed correctly



3) Foam installed folded over, contacting the line


Recommendation/Instructions

Please inspect the Engine cover and Compare to the pictures to see if the foam is folded.

- 1) If the Foam is deformed then replace the cover.
- 2) If a burning odor was found replace the cabin filter.



2) Foam is Deformed from heat



1) Cover and foam installed Correctly

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION