



Service Bulletin

PRELIMINARY INFORMATION

Subject: Steering Wheel Drivers Airbag Rattle Click or Tick Noise

Models: 2015 Chevrolet Colorado

2015 GMC Canyon

This PI was superseded to update repair information. Please discard PIT5373.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The customer may report there is a slight rattle, click or tick noise from the steering wheel area and may also report that lightly resting their hand on the driver's airbag may quiet the noise.

Recommendation/Instructions

A revised steering wheel has been released to service to reduce this noise. Reference the Electronic Parts Catalog for proper steering wheel part number per vehicle options.

Note: Do NOT replace the SIR Coil or Driver's Air Bag for this concern.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
7440130	Replace Steering Wheel	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION