



Service Bulletin

PRELIMINARY INFORMATION

Subject: Sway Bar Not Present On Vehicles Equipped With 4-Wheel Independent Suspension (RPO FE1)

Models: 2014 - 2016 Chevrolet Corvette
Equipped with 4-Wheel Independent Suspension (RPO FE1)

This PI was superseded to update Model Years. Please discard PIC6009.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A dealer or customer may inquire as to whether or not a rear sway bar can be added to a vehicle that was not originally equipped with one. The rear sway bar is part of the Z51 Performance Package.

Recommendation/Instructions

Important: GM does NOT recommend or support this modification. Do NOT install a rear sway bar on a vehicle not originally equipped with the Z51 Performance Package

The FE1 suspension system was designed and tested without a rear sway bar. Installing a rear sway bar on a FE1 (non-Z51) vehicle may cause concerns with vehicle control, ride and handling.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION