



Service Bulletin

PRELIMINARY INFORMATION

Subject: Top Front Strut Mount Appearance Concern

Models: 2016 Chevrolet Camaro

Condition/Concern

Some customers may comment on the appearance of the front struts inside the shock towers. They may see what appears to be a rust-like material around the rim of the upper strut mount. This can be seen in the picture below.



This concern is not actually rust, rather, is caused by an applied layer of rubber to the top of the strut that does not completely cover the nylon underneath. This appearance will not affect performance or durability of the vehicle. It is strictly a cosmetic concern..

Recommendation/Instructions

Important: IMPORTANT: Do NOT replace any parts for this condition. Engineering is aware of the condition and working on a resolution. This PI will be updated once a repair becomes available. New parts are expected to be ready in the late 1st / early 2nd quarter of 2016 to resolve this concern.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION