



Service Bulletin

PRELIMINARY INFORMATION

Subject: Remanufactured Engine With Oil Consumption, Misfires, Lack of Power, or Rough Running Engine

Models: 2009-2010 Buick Enclave LaCrosse
2009-2010 Cadillac CTS SRX STS
2009 Chevrolet Camaro
2009-2010 Chevrolet Traverse
2009-2010 GMC Acadia
2009 Pontiac Torrent
2009-2010 Saturn Outlook Vue
Equipped with HFV6 3.6L LLT Engine

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Some customers may comment on any of the following concerns on remanufactured HFV6 engines.

Condition/Concern

Misfires, Lack of Power, Rough Running Engine, or Oil Consumption

Recommendation/Instructions

Engineering is aware of a concern on these engines and is working on a repair. At this time for the engine Part Numbers listed below, stop trying to diagnose these concerns and don't make any further repair attempts until notified by DSL message or this PI is updated.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Part #'s 19210824, 19210825, 19303671, 19303673, 19210835, 19210836 and 19210837 - All are remanufactured engines built on or after 11/24/2015 with the following serial #'s

40605188, 40605190, 40605192, 40605193, 40605194, 40605195, 40605196, 40605199, 40605200,
40605205, 40605206, 40605208, 40605179, 40605141, 40605135, 40605094, 40605095, 40605096,
40605097, 40605098, 40605103, 40605106, 40605107, 40605117, 40605119, 40605121, 40605123,
40605124, 40605125, 40605126, 40605127, 40605128, 40605129, 40605130, 40605131, 40605099,
40605100, 40605101, 40605102, 40605104, 40605105, 40605108, 40605109, 40605110, 40605111,
40605112, 40605113, 40605114, 40605115, 40605116, 40605118, 40605058, 40605059, 40605060,
40605061, 40605062, 40605063, 40605064, 40605065, 40605066, 40605067, 40605068, 40605069,
40605070, 40605071, 40605072, 40605073, 40605074, 40605075, 40605076, 40605078, 40605079,
40605080, 40605081, 40605082, 40605083, 40605084, 40605085, 40605172, 40605143, 40605146,
40605148, 40605136, 40605137, 40605142, 40605145, 40605149, 40605150, 40605151, 40605122,
40605134, 40605039, 40605220, 40605225, 40605189, 40605191, 40605201, 40605202, 40605203,
40605204, 40605207, 40605181, 40605221, 40605168, 40605169, 40605171, 40605173, 40605175,
40605176, 40605177, 40605178

See the metal tag on the right side of the engine for this information.

(refer to TSB 06-00-89-031)

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION