



Service Bulletin

PRELIMINARY INFORMATION

Subject: Compass On Radio Display Always Showing North

Models: 2014 Buick Regal, LaCrosse (RPO IO5)

2014 Cadillac ATS (RPO UA3 without UY4), CTS VIN A (RPO IO5), SRX (RPO RAO without UY4), XTS (RPO IO5)

2014 Chevrolet Corvette (RPO RAO without UY4), Impala (RPO IO5), Silverado 1500 (RPO IO5)

2014 GMC Sierra 1500 (RPO IO5)

Condition/Concern

Some customers may comment the compass on the radio display always shows North (N).

Recommendation/Instructions

Reprogram the radio with the latest calibrations using TIS-2-WEB.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810335	Radio Reprogramming with SPS	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION