



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** B1446 Or B1447 On 09 Saturn Vue Hybrid After Module Replacement

**Models:** 2009 Saturn Vue Hybrid

*This PI has been superseded to edit the handling process. Please disregard PIC5141.*

### Condition/Concern

A B1446 or B1447 may appear after module replacement or after performing the Canada upgrade outlined in the latest version of bulletin 15-08-44-001 on a 2009 Saturn Vue Hybrid due to a software anomaly in the setup procedure.

The 2009 Saturn Vue Hybrid is not equipped with an OnStar backup battery.

### Recommendation/Instructions

Please record the new module P/N, STID, MEID, MIN, MDN and call GM Technical Assistance for further assistance.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
602058	Onstar Programming	.3 hrs

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION