



Service Bulletin

PRELIMINARY INFORMATION

Subject: Oil Consumption With Nothing Found

Models: 2015-2016 Cadillac Escalade
2015-2016 Chevrolet Suburban, Tahoe
2014-2016 Chevrolet Silverado 1500
2015-2016 GMC Yukon Yukon XL
2014-2016 GMC Sierra 1500
Built with RPO's 4.3L 5.3L 6.2L L83 L86 LV3

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Customers may comment on an engine oil consumption.

Recommendation/Instructions

If the oil consumption is noted and all the Si documents have been followed.

Remove the vacuum line from the back of the vacuum pump and inspect for oil.

If oil is found then reference PIT5361 Diagnostic Tip - Additional Brake Pedal Effort.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION