



Service Bulletin

PRELIMINARY INFORMATION

Subject: HPCM Fault DTC P1A56 Hybrid Battery Voltage Discharge Circuit

Models: 2011-2015 Chevrolet Volt

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Technicians may call and comment the vehicle has dtc P1A56 (type C dtc) stored in history.

Recommendation/Instructions

Engineering as found that P1A56 will set falsely with no effect

If there are any other dtc's stored address those dtc's by following published diagnostics.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION