



Service Bulletin

PRELIMINARY INFORMATION

Subject: Object Detection Unavailable Message Displayed on Radio for Vehicles Not Equipped with RPO UD7

Models: 2015 Chevrolet Silverado HD
2015 GMC Sierra HD
Equipped with IO3 Radio
Not Equipped with RPO UD7 Object Detection

Condition/Concern

Some customers may complain of an "Object Detection Unavailable" message on the radio display when shifting into reverse.

Recommendation/Instructions

If this concern is encountered, reprogram the radio with the latest software to correct this concern.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810335	Radio Reprogramming with SPS	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION