



Service Bulletin

PRELIMINARY INFORMATION

Subject: Surge While Driving Around 35 MPH And Above

Models: 2015 Chevrolet Malibu

This PI was superseded to update Administrative Details. Please discard PIP5254.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some vehicles equipped with a 6T40 MNH transmission and a 2.5L LKW engine may have a surge, shudder, vibration, chugle felt while driving a steady speed near and/or above 35 mph with no DTCs nor engine mis-fire counts.

Recommendation/Instructions

If this concern is present, contact TAC at number you have been provided for tracking and information

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION