



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - BCM DTC U0100 and/or U0101

Models: 2008 Chevrolet Express
2008 GMC Savana

This PI was superseded to update Recommendation/Instructions. Please discard PIT4482.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The dealer may find DTC(s) U0100 and/or U0101 set in the BCM when checking for codes. These codes will usually be set with other communications codes. These codes can be set as current or history. The BCM may set U0100 and/or U0101 as a false code(s) when other communications codes set.

Recommendation/Instructions

Disregard DTC U0100 and/or U0101 set in the BCM unless it is also set in other controllers. If other communications codes are set, follow the diagnostics in SI for the appropriate code.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION