



Service Bulletin

PRELIMINARY INFORMATION

Subject: Goodwrench SRTA GM Remanufactured 4T65E Cooler Line Fittings Different Than OEM

Models: 1999-2000 4T65e Goodwrench SRTA Reman Remanufactured Transmission Assemblies

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Cooler line fittings/connectors installed on 4T65E Goodwrench Remanufactured Transmission Assemblies may be different than OEM.

Condition/Concern

Cooler line fittings/connectors that come with the 4T65E GM Remanufactured Transmission may not be the same as OEM, quick connect verses inverted flare.

Recommendation/Instructions

After verifying the cooler line fittings/connectors that came with the Goodwrench Remanufactured Transmission Assembly are different than OEM, and the OEM fittings cannot be installed into the replacement trans assembly due to case housing thread size, contact TAC at the number you have been provided for additional information.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION