



Service Bulletin

PRELIMINARY INFORMATION

Subject: Turn Signal Indicator Does Not Match Audible Warnings (Click-Clack)

Models: 2010-2016 GMC Terrain
2010-2016 Chevrolet Equinox

This PI was superseded to update Model years. Please discard PIT5302.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Customer may have a concern where the turn signal indicators on the IPC do not match the audible warnings (Click-Clack) from the speaker.

Recommendation/Instructions

Important: Do NOT replace or update software in any control modules.

Inspect battery condition with the GR8 (EL-50313) and verify the charging system is operating correctly.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4041512	Battery Charging and Testing	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION