



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** GM Accessory Fender Flares Loose

**Models:** 2015-2016 Chevrolet Colorado  
2015-2016 GMC Canyon

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

The customer may state the accessory fender flares are pulling away from the fender and/or appear loose.

### Recommendation/Instructions

Replace the flare kit with a new kit from stock.

Pay specific attention to the updated installation instructions in Service Information.

The correct application of the flares to the vehicle is important for retention.

The accessory kits and instructions have been updated.

The new kits have an additional nut and bolt used in each of the rear flares.

If the dealer has an older kit in stock reuse 2 of the nuts and bolts from the original set.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
* 0580168	Remove and Install Accessory Fender Flares	1.7 hr
* This is a unique labor operation for bulletin use only		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION