

[Next Unread Message](#)**View Message**

Sent on 01 02 2015 **Expires on** 01 16 2015
From Parts and Service Division
Subject Request for Info: 2014-2015 MDX & RLX MIL On with DTC P0154 or P0134 Stored

Message PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Info: 2014-2015 MDX & RLX MIL On with DTC P0154 or P0134 Stored

This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this i/N message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2014-2015 MDX & RLXs with a complaint that the Malfunction Indicator Lamp (MIL) is on and DTC P0154 (Front Air Fuel Ratio Sensor [Bank 2, Sensor 1] Heater System Malfunction) or P0134 (Rear Air Fuel Ratio Sensor [Bank 1, Sensor 1] Heater System Malfunction) is stored. To fully understand the cause of this condition, AHM would like to collect specific information from the vehicle prior to any repair.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. DTC P0154 or P0134 must be stored.

Action Required

If you have or know of such a vehicle, please [click here](#) to print questionnaire, fill out, and fax to Technical Research & Support (TRS) Group at (310) 224-4085.

Thank you.

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.