



Countries: TAIWAN, UNITED STATES, GUAM, KOREA, SOUTH KOREA
Availability: ISIS
Major System: ENGINES
Current Language: English
Other Languages: NONE
Viewed: 273

Document ID: IK1200752
Revision: 1
Created: 4/16/2012
Last Modified: 5/4/2015
Author: Aaron Mimbs

[Less Info](#)
[Hide Details](#)
Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 12	Not Helpful 3
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	--------------------------	-----------------------------

Title: 2010 MaxxForce 7 UVC Harness

Applies To: All 2010 EPA MaxxForce 7

CHANGE LOG


Please refer to the change log text box below for recent changes to this article:

05/04/2015 - Author updated for feedback purposes and se the coding since it was not set.


When you have a 2010 EPA MaxxForce7 with an injector open circuit or an injector short code ACTIVE then perform all the injector and harness checks prior to replacing any components.

For diagnostic informantion regarding the fault codes see [EGES485](#)

If the harness and injector checks all come out with in specification then replace the UVC harness for the injector that has the ACTIVE code. Then clear the code and road test.



For UVC harness removal tool see [SFN1071](#)



If the code is still present after replacing the harness open a case file.

 Hide Details

Feedback Information

Viewed: 272

Helpful: 12

Not Helpful: 3

No Feedback Found

Copyright © 2015 Navistar, Inc.