



Countries: BAHAMAS, BOLIVIA, BELIZE, CANADA, CHILE, TAIWAN, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR, EL SALVADOR, TRINIDAD AND TOBAGO, UNITED STATES, URUGUAY, VENEZUELA, ARUBA, NICARAGUA, PERU, PUERTO RICO, Curaçao, GUAM, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, KOREA, SOUTH KOREA, PANAMA

Document ID: IK1200717

Availability: ISIS, FleetSIS, Body Builder

Revision: 4

Major System: ENGINES

Created: 2/2/2012

Current Language: English

Last Modified: 10/29/2015

Other Languages: NONE

Author: Will (Mark) Wiley

Viewed: 6073

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 352	Not Helpful 447
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	---------------------------	-------------------------------

Title: Active Code 1081-1 or 1213-5

Applies To: ProStar/WorkStar/TranStar with 2010 EPA Maxx Force 11 or 13

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

10/29/2015 - Updated link to SM template.
10/29/2015 - Added templates for all N13 years.

DESCRIPTION

If code 1081 or 1213 become active after updating the ECM calibration, [CLICK HERE](#) for the Service Maxx template to correct this parameter issue.

For instructions on installing a template: Go to [IK1200603](#)

POSSIBLE DIAGNOSTIC TROUBLE CODES

DTC	FMI	MODULE	DESCRIPTION
1081	1	Engine	WTSL Light Diagnostics
1213	5	Engine	MIL Light Diagnostics

Hide Details

Feedback Information

Viewed: 6072
Helpful: 352
Not Helpful: 447

No Feedback Found