



Countries: BAHAMAS, BOLIVIA, BELIZE, CANADA, CHILE, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR, EL SALVADOR, TRINIDAD AND TOBAGO, UNITED STATES, URUGUAY, VENEZUELA, ARUBA, NICARAGUA, PERU, PUERTO RICO, Curaçao, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, PANAMA
Document ID: IK1600183
Availability: ISIS, FleetSIS
Revision: 10
Major System: CAB / SLEEPER / HOOD
Created: 5/9/2013
Current Language: English
Last Modified: 7/23/2015
Other Languages: NONE
Author: Jeff McIntosh
Viewed: 2956

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 18	Not Helpful 2
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	--------------------------	-----------------------------

Title: Offensive Odors Inside Cabin

Applies To: Post 2010 ProStar

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

7/23/2015 - Fixed links
 5/23/2014 - Updated "Warranty Information" section to explain coding for failure dates.

DESCRIPTION

- Driver complaint of offensive odors in the cab.

TOOLS REQUIRED

- General hand tools
- 1/4 inch drill bit
- Drill

PARTS INFORMATION

- Cowl Tray Kit : P/N 2511806C91

REPAIR PROCEDURE

Click on the following items:

- [Diagnostic Flow Chart](#)
- [Cowl Tray Installation Instructions](#)

OTHER RESOURCES

Click on the following items:

- [Exhaust Leak Troubleshooting for 2010 Emission](#)
- [PDOG Clamp](#)
- [Cowl Tray to Cab Seal Installation Procedure](#)
- [Exhaust Manifold Ring Seal Removal / Installation](#)
- [Exhaust Manifold Gasket Removal and Installation Procedure](#)

WARRANTY INFORMATION

NOTE:

- File separate claim sections when addressing leaks at the cowl tray and the exhaust manifolds.
- If vehicle is beyond standard (01) warranty cowl tray repairs can be claimed under warranty code 40, under a separate claim section. This repair should **NOT** be done proactively (repair must address an "Odor in Cab" complaint). File claim using SRT A40-13665-1, and coding to group 13665.
- All claims submitted under warranty code 40 must be filed by Feb. 28, 2014

Group	Noun
16034 - Cab Exterior Appointments	301 Cowl Tray

SRT Description	SRT Code Link (Model)		SRT(hr)
Cowl Tray, Replace (Includes Kit Install)	R16-1301A	(ProStar)	0.7

 Hide Details

Feedback Information

Viewed: 2955
 Helpful: 18
 Not Helpful: 2

No Feedback Found