



Previous Screen

Welcome: chrismk2

◀ Product: NO EQUIPMENT SELECTED
Model: NO EQUIPMENT SELECTED
Configuration: NO EQUIPMENT SELECTED

Technical Information Bulletin

A/C Refrigerant Quantity Is Incorrect for CT660 On Highway Trucks{7000}

Media Number -TIBU7226-00

Publication Date -21/08/2013

Date Updated -21/08/2013

Caterpillar: Confidential Yellow

i05425806

A/C Refrigerant Quantity Is Incorrect for CT660 On Highway Trucks{7000}

SMCS - 7000

On Highway Truck:

CT660 (S/N: TGA1-UP; TGD1-UP; TJD1-UP; TEJ1-UP; TRK1-UP; TKL1-UP; TEM1-UP; TEP1-UP; TGR1-UP; TGS1-UP; TJS1-UP; TGT1-UP; TGW1-UP; TSW1-UP; TEY1-UP; TSY1-UP; TEZ1-UP; TGZ1-UP)

Introduction

There is a problem with the refrigerant quantity, listed in System Operation, Disassembly and Assembly, and Specifications, UENR1844-01, for CT660 On Highway Trucks.

Problem

In table 14 in chapter 6 of System Operation, Disassembly and Assembly, and Specifications, UENR1844-01 the refrigerant quantity is incorrect.

Solution

The refrigerant quantity for CT660 On Highway Trucks (all engines) is 1.70 kg (3.75 lb), 1700 g (60 oz)

[Copyright 1993 - 2013 Caterpillar Inc.](#)

[All Rights Reserved.](#)

[Private Network For SIS Licensees.](#)

Fri Sep 6 13:05:30 CDT 2013

chrismk2