

# Technical Service Bulletin

#### 19 Customer states engine overheating; no MIL or DTC - Repair Authorization

19 15 57 2040043/1 March 12, 2015.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5, A5 cabriolet, A6, A7, Q5, Q7, A8	2014 - 2015	All	3.0T engine

## Condition

- Customer states that engine overheats.
- No MIL.
- No related DTCs are stored.

# **Technical Background**

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the overheat condition for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

#### **Production Solution**

No changes to production have been made, as no issue has been identified.

#### **Service**

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

- 1. Verify the condition, if possible.
- 2. If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Attach the DTC and diagnostic log to the TAC ticket.

#### Warranty

This TSB is informational only and not applicable to any Audi warranty.

© 2015 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



### **Additional Information**

All parts and service references provided in this TSB (2040043) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2015 Audi of America, Inc.

Page 2 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.