

Technical Service Bulletin



46 Ceramic brakes - Repair Authorization

46 15 16 2034143/4 June 29, 2015. Supersedes Technical Service Bulletin Group 46 number 14-85 dated July 14, 2014 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
R8	2012 - 2015	All	Ceramic brakes
RS 5, RS 5 Cabriolet	2012 - 2015	All	Ceramic brakes
RS 7	2014 - 2016	All	Ceramic brakes

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised header data (Added model and model years)
3	7/14/2014	Revised <i>Service</i> (Updated recording submission instructions)
2	4/14/2014	Revised header data (Update VIN information)

A TAC ticket must be opened for any repairs related to the ceramic brakes.

Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

1. Verify the complaint.
2. If the vehicle is within the New Vehicle Limited Warranty, complete the attached brake acoustic questionnaire.
3. If the complaint is noise-related, obtain a sound or video recording (a cell phone recording is acceptable as long as the noise can be clearly identified).
4. Attach the completed questionnaire and sound or video recording to the TAC ticket. A sound recording is necessary to help determine the root cause of the noise and to help resolve the concern. If you are not able to attach these documents to the TAC ticket, email them to **chassis@audi.com** and notify TAC.
5. Contact a TAC consultant before proceeding with any repairs.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB (2034143) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.