

# Technical Service Bulletin



## 91 Generation III radio: Loose or broken control knobs

91 15 89 2017425/5 June 3, 2015. Supersedes Technical Service Bulletin Group 91 number 14-30 dated April 7, 2014 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5, A5 Cabriolet, Q5	2010 - 2016	All	CAN Radio

## Condition

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised header data (Added model years)
4	4/7/2014	Revised header data (Added model years and PR codes)
3	3/18/2010	Revised header data (Added models and model years)

On generation III Concert and Symphony radios (Figure 1), the control knob or volume knob is broken or loose.



Figure 1. A generation III radio.

## Technical Background

Knobs may be damaged by outside influence.

## Production Solution

Not applicable.

# Technical Service Bulletin

---



## Service

The knobs can be replaced individually and are available as accessories.

## Warranty

This damage is due to outside influence and is not covered by any Audi warranty.

## Required Parts and Tools

Part Number	Part Description	Quantity
8T0059528	Control knob replacement kit	1*

\* This part number is a kit that contains one volume knob and one control knob.

## Additional Information

All parts and service references provided in this TSB (2017425) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.