



# Tech Tips

---

TT 26-15-01

Date: February 20, 2015

**2009-2010 Routan equipped with 3.8 L or 4.0 L - Stumble/Jerk at low speeds or while stopping, C121C stored in the ABS module (sporadic)**

---

Replace the EGR valve and perform an extended road test to verify the repair.