

Tech Tips

TT 61-08-07


Date: 2008

2007-2015 EOS - Roof Pillar Flap Components

February 20, 2015: Update to Model Year.

If diagnosis leads to a concern with either roof pillar flap, it may NOT be necessary to replace the complete flap assembly. Individual components of the roof pillar flap are available.

See ETKA illustration 871-50 for exploded component view and part listing.



POS	PART NUMBER	NAME	REMARKS	QTY	MODEL
1	1Q0 868 851 C	roof brace flap	left	1	
	05/06-05/08 82V	titanium black			
(1)	1Q0 868 852 C	roof brace flap	right	1	
	05/06-05/08 82V	titanium black			
3	1Q0 871 257 C	trim for roof bracing flap	left also use: POS.6	1	
	05/06-05/08 83V	titanium black			
(3)	1Q0 871 258 C	trim for roof bracing flap	right also use: POS.6	1	
	05/06-05/08 83V	titanium black			
5			for this use: position:	1	
6	7L0 867 208	retaining clip		16	
8	1Q0 871 111 A	adjusting screw		6	
10			for this use: position:	1	
11	1Q0 872 473 C	support part	left a. right	2	
12-14			for this use: position:	1	
15	1Q0 872 463	pivot pin roof brace flap		1	
16	1Q0 871 271	protective edging	33MM	2	
17	1Q0 871 129 B	clip		12	
20-24			for this use: position:	1	