

# Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Beetle, Beetle Convertible	2013-2015	2.0T (CPPA, CPLA)	All	All	All
Jetta, Passat, Beetle, Beetle Convertible	2014-2015	1.8T (CPKA, CPRA)	All	All	All
GTI	2015	2.0T (CXCA)	All	All	All
Golf, Golf SportWagen,	2015	1.8T (CXBA, CXBB)	All	All	All

## Condition

24 15 02 March 24, 2015 2040179

### DTC P2014 Intake Manifold Position Sensor -G336- Replacement

Direction on proper part replacement when diagnosing fault code P2014 in the ECM.

## Technical Background

Information only.

## Production Solution

Information only.

## Service

If after performing Guided Fault Finding (GFF) for fault code P2014 in the ECM, the Intake Manifold Runner Position Sensor -G336- requires replacement, only replace the sensor, NOT the entire intake manifold assembly. Claims for intake manifolds will be debited unless directed and documented by GFF.



### Note:

**When claiming Intake Manifold Runner Position Sensor -G336- use PID 2465.**



# Technical Bulletin

---

## Warranty

Information only.

## Required Parts and Tools

Information only.

## Additional Information

**All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.**