



Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All Models	2014-2015	All	All	All	All

Condition

00 15 01 March 19, 2015 **2036935** Supersedes V001410 dated October 1, 2014 to include additional model and model year applicability.

By-Pack at Delivery

Components may be missing from the by-pack at delivery.

Technical Background

Components missing from the by-pack should be claimed in one of two ways. (Warranty or Transportation) Understanding when to claim one versus the other is very important.

Production Solution

Not applicable.

Technical Bulletin

Service

Note:

During the launch periods you are required to attach pictures of the by-pack and labels to the VTA ticket. Please use the pictures in this document as reference when you are taking your pictures.

Note:

These two MDI cables for iPod/iPhone shown below are the only cables that will work with the new MY15 Golf/GTI.



Note:

PR code UF8 indicates the vehicle was produced with Part number 5N0035554H (green collar above). The MDI cable that is provided with all VW vehicles is Part Number 5N0035554B (blue collar above). ALL MDI cables, that are not 5N0035554B, found with the vehicle produced without PR Code UF8 (incorrect, damaged, not functioning, etc.) will not be considered for reimbursement through New Vehicle Limited Warranty claim type.

Tip:

By-Pack is a term used to describe the bag that is delivered with the vehicle that contains the parts to be installed at PDI, i.e. Wheel Center Caps, Lug Caps, Wiper Blades, Etc.

Inspection Procedure

1. When a vehicle is delivered to the dealer the by-pack should be inspected for condition and contents.

Many of our vehicle's by-packs have contents labels in English to help with this inspection.

For the bags that do not have English translated contents labels on the by-pack the inspection can still be done but to a limited extent.

2. In a case where the bag is found open in any way and parts are missing, the claim should be filed as a transportation claim.

ONLY if the bag is completely sealed and parts are found missing should the claim be filed under warranty.

Technical Bulletin

Note:

Make sure to properly document the condition of the bag whether it is sealed (undisturbed) or open (disturbed) and the components that are missing on the transportation delivery form. The transportation delivery form may be requested when a transportation claim is filed.



- The condition of the bag is the most important observation to be made.
- A bag found completely sealed and missing items is a normal pre-delivery warranty claim.
- A bag that is open in any way and missing parts should be claimed as a transportation claim.
- Pictures of the condition of the bag will also be important when trying to claim warranty or transportation as they may be requested.

Figure 1

VOLKSWAGEN DE MEXICO					
MODEL	UTN	PKN	RESERVATION		
162UJ1	2442141/021304404	02142210551	0004121957		
POS	PART NUMBER	DESCRIPTION	QTY	1	2
		TUNING KIT			
01	178.000.010.0	SAVCHO DE ARRABTRE ASCHL.EPPHRE	1		
02	007.000.000.0	PALANCA LEMPIA PALANCA LEMPIA	1		
03	008.001.047.0 .01U	WHEEL TRIM TAPACUIDE INTERNAI BADEIENLENDE	4		
04	107.010.100.7	RIZ PROTECTION PROTECTION PARA RIZ FOLDEDCHAUTE	4		
05	008.007.000.0 .009	WHEEL PLATE BOP... IN ENTRAO, KEMHEI...ENTRADO	1		
06	100.007.001	FRONT BUMPER TAPA FRENTE DELANTERA STOPFACHUENABECKUNG VORN	1		
07	100.007.001	REAR BUMPER TAPA FRENTE TRARRA STOPFACHUENABECKUNG HINTEN	1		
08	100.010.007	ELECTRIC LIGHTER ELEKTRISCHER ZIGARETTENANZUEHNER	1		
TOTAL AMOUNT OF PIECES IN BAG:			17		
TOTAL AMOUNT OF PIECES NOT INCLUDED IN BAG:			0		

Figure 2

VOLKSWAGEN DE MEXICO					
MODEL	UTN	PKN	RESERVATION		
162UJ1	2442141/021304404	02142210551	0004121957		
POS	PART NUMBER	DESCRIPTION	QTY	1	2
09	100.007.000	CLIPPER SCHLUSSEL	1		
10	008.010.700.7	OPERATING MANUAL/INSTRUCION EXTRAORDINARIA	1		
11	008.010.701.00	OWNER'S MANUAL MANUAL A BORDO EXTRAORDINARIO	1		
TOTAL AMOUNT OF PIECES IN BAG:			17		
TOTAL AMOUNT OF PIECES NOT INCLUDED IN BAG:			0		
1. TRANSPORTISTA		2. PUERTO			

Figure 3

Technical Bulletin

- There may be multiple contents labels on the bag.
- Using the label(s) will help determine the proper contents of the bag (figures 2 and 3).
- The VIN is indicated on the bag which can also be used to determine if the by-pack is the correct one for the car.
- Taking a picture of this label(s) can also assist in determining the root cause of the problem.

3. The contents inspection is the third part of the inspection and will determine if any action is necessary in terms of filing claims.

- A claim may be filed but the claim type will be determined by whether the bag is opened or closed.

 **Note:**

Information on every factory's by-pack label(s) can be found in service circular VSP-13-01, on ServiceNet.

 **Note:**

Wheel Locks are no longer factory installed parts and therefore are not covered under warranty when missing at PDI. Please reference Service Circular VSP-13-02, on Service Net, for info on the procedure for missing wheel locks.

Warranty

Information only.

Required Parts and Tools

No Special Parts required.

No Special Tools required.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.