

Tech Tips

TT 61-08-05

Date: 2008

2007-2015 Eos – Convertible Top Repair Tip

March 20, 2015: Update to photos.

If, during diagnosis of the convertible top, the adjuster arm for the front lock is found damaged, order part number 1Q0898499 or latest supersession. This one part number will include both sides in the package. Adjuster arm location is shown below with painted roof pillar panel removed.




Figure 1



Das Auto.

Service Information



Figure 2