



# Warranty Policies and Procedures Bulletin

## Audi Warranty

Number: AWA-15-02

Date: Jan 16, 2015

Subject: Intake Manifold Limited Warranty Extension  
(include 2012 MY)

**Supersedes AWA 13-08**

Dealers: United States and Puerto Rico

This document modifies the Audi Warranty Policies and Procedures Manual.

This Warranty Bulletin supersedes AWA 13-08 dated Aug 21, 2013 due to expansion of the Limited Warranty Extension to include certain 2012 Model Year vehicles. All information from the original bulletin is included here. AWA 13-08 is deactivated as of this date.

### Effective Reception Date for coverage:

1. Aug 20, 2013: Vehicles with U17 warranty key AND production date Nov 14, 2010 and prior
2. Jan 13, 2015: Vehicles with U17 warranty key AND production date Nov 15, 2010 and later

### Warranty Keys and Production Dates found in Elsa.

Audi is extending the Emissions Control Systems Warranty for the intake manifold under specific conditions to 10 years or 120,000 miles, whichever occurs first, from the vehicle's original in-service date for certain 2008-2012 Model Year Audi 2.0 TFSI Engine vehicles with engine code CBFA, CCTA, and CETA. The vehicle's original in-service date is defined as the date the vehicle was delivered to either the original purchaser or the original lessee; or if the vehicle was first placed in service as a "demonstrator" or "company" car, on the date such vehicle was first placed in service. The warranty extension is fully transferable to subsequent owners.

Certain states have voluntarily adopted California-mandated emissions warranties only for vehicles equipped to meet California's Partial Zero Emissions Vehicle (PZEV) emissions requirements. These vehicles can be identified by inspecting the Vehicle Emission Control Information Label located under the hood. Because of this, the owner of a vehicle equipped to meet California's PZEV emissions requirements living in one of these states may have warranty rights that exceed the extended warranty offering described in this bulletin. Owners should refer to the warranty information that came with their vehicle for additional details as to whether or not this applies to their vehicle.

### What is the Problem

Audi has determined that, under specific conditions a faulty intake manifold may cause the Malfunction Indicator Lamp (MIL) on the instrument cluster to illuminate due to the presence of specific fault codes caused by this component,

The MIL is part of the on-board diagnostic system. Please refer to the owner's manual for additional information about the MIL. In some locales, an illuminated Malfunction Indicator Lamp could cause the vehicle to fail an IM emissions inspection, and the vehicle registration application could be denied.

# Warranty Policies and Procedures Bulletin

---

Be aware that other conditions (unrelated to the issue described in this bulletin) may cause the MIL in the vehicle to illuminate. Customers should be prepared to cover all diagnosis and repair costs for these other, unrelated conditions.

## What is covered under this Warranty Extension

This warranty extension covers only the diagnosis and replacement of the intake manifold.

## What is not covered under this Warranty Extension

- ▶ Any damage or malfunctions caused by installation of non-EPA or non-CARB certified parts, or parts that alter the performance of the engine, engine controls, or exhaust system, such as the installation of engine management components (chipped” or “tuned” ECMs) not approved by Audi.
- ▶ Other conditions *unrelated* to a faulty intake manifold that may cause the MIL to illuminate. These conditions may require repairs that are needed for proper diagnosis of the underlying condition. Any repairs that are (1) necessary for proper diagnosis of these other conditions or (2) required to bring the vehicle up to factory specifications are not covered by this warranty extension.
- ▶ Damage or malfunctions caused by outside influence, such as damage due to an accident, or vehicle misuse or neglect as well as repairs that are (1) necessary for proper diagnosis of these other conditions or (2) required to bring the vehicle up to factory specifications are not covered by this warranty extension.

## Warranty Extension Coverage Limitations

The warranty and maintenance information that came with the owner’s vehicle contains information on the limited warranties applicable to their Audi. Owners should read these limited warranties carefully to determine their warranty rights and obligations, as this information also applies to the coverage provided to them in this warranty extension

**Claim Processing: Claim Type – 110 SN – 2447**

**Warranty Key: U17 Intake Manif. EXT 10/120,000 US ONLY** is assigned in Elsa to identify vehicle eligibility.

Reimbursement is applicable only to the repairs described in this Warranty Bulletin.

Contact Audi Warranty for questions or concerns: 866.677.2834 or [AudiWarranty@Audi.com](mailto:AudiWarranty@Audi.com).

Information in this Bulletin is Warranty Policy. All warranty claims must be submitted in accordance with the most recent edition of the Audi Warranty Policies and Procedures Manual. Claims are subject to review and/or audit by Audi Warranty.