



Tech Tips

TT 01-15-02

Date: July 3, 2015

2003-2010 7L Touareg - Scan tool lock up/Scan stops at 33%

While performing a GFF scan (with the newer version of ODIS software), the scan tool can lock up at 33%. Disconnect the VAS 5054 A wireless transmitter head for 10 seconds and plug back in, the scan should continue automatically. If not, cycle the ignition key on and off. The scan should automatically continue.