

Date	Expiration	Release	Page
06.2015	06.2015	1	1(3)

Release 1: Initial release.

SEALING IN AUXILIARY HEATER COMPARTMENT

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, seal a tube passage between the Auxiliary heater compartment and the heating duct in the passenger's compartment.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS <i>Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.</i>	
Model	VIN
X3-45 coaches Model Year : 2015	From 2PCG33499EC735819 up to 2PCG33497EC735866 incl.
X3-45 VIP commercial use Model Year : 2015	The following individual vehicles: 2PCC33497EC735820; 2PCC33490EC735822 2PCCS349XEC735829; 2PCCS3498EC735831 2PCCS3499EC735840
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

Order the following parts:

Part No.	Description	Qty
684517	Simson sealant (Cartridge)	1

NOTE

Material can be obtained through regular channels.

Date	Expiration	Release	Page
06.2015	06.2015	1	2(3)


PROCEDURE




DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.


Lift the road-side wheel fender.



Seal the tube opening in the ceiling of the Auxiliary heater compartment with #684517 Simson sealing compound.



Date	Expiration	Release	Page
06.2015	06.2015	1	3(3)



PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately xxx hour.

OTHER

VBC Bulletin	N/A
Fail Code	18.02
Defect Code	09
System Condition	B
Causal Part	684517

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.