

Special Bulletin

SP15-339

Date	Expiration	Release	Page
08.2015	08.2017	1	1(3)

Release 1 Original release

August 01, 2015

CURB SIDE FLOOR NOSING HARDWARE

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, replace hardware on the aisle step curb side nosing.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS		
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.		
Model	VIN	Unit number
X3-45 Commuter Model Year : 2014, 2015	Single vehicles 2PCG33495 ~~EC73~~ 5590 , 2PCG33498 ~~EC73~~ 5602 . And from 4RKG33497 ~~E973~~ 7001 up to 4RKG33493 ~~E973~~ 7027 incl.	2490, 2491 And from 2492 up to 2518
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.		

MATERIAL NEEDED

Order the following parts:

Part No.	Description	Qty
5001119	SCREW TP BDG PH #8x3/4 SS	9

NOTE

Material can be obtained through regular channels.

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

1. Remove the kick plate. To access the step nosing.

Keep modesty panel hardware (Fig. 1).

Part number reference:

Screw	5001871 qty 3
Flat	500411 qty 9
Lock	500477 qty 3
Cap	500772 qty 3




Figure 1

2. On the step nosing, install new replacement hardware 5x 5001119, at indicated locations. (Fig. 2)




Figure 2

Date	Expiration	Release	Page
08.2015	08.2017	1	3(3)

3. Install the kick plate back on the modesty panel using hardware reserved previously.





Figure 3

4. Install new replacement hardware 5001119, qty 4 at indicated locations.



PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately 30 minutes.

OTHER

VBC Bulletin	N/A
Fail Code	18.02-1
Defect Code	09
System Condition	B
Causal Part	500640

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.