



Countries: CANADA, UNITED STATES **Document ID:** IK2200136
Availability: ISIS, Bus ISIS **Revision:** 0
Major System: BUS BODY **Created:** 8/13/2015
Current Language: English **Last Modified:** 9/18/2015
Other Languages: NONE **Author:** Jeff Novak
Viewed: 99

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 0	Not Helpful 0
---------------	------------------------	---	----------------------	-----------	----------------------	------------------	----------------------

Title: RE Bus with 2630:16 - CACOT Undercooling

Applies To: RE Bus with 2013 OBD MaxxForce DT engines

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

08/31/2015 - Initial Article Release

DESCRIPTION

Rear Engine (RE) Buses with OBD MaxxForce DT engines may experience a 2630:16 - CACOT Undercooling fault code while operating in warmer climates. If the following items were performed and the unit is still experiencing the fault then a case file should be opened with technical services.

- Calibration is current (CAL ID - EGR3)
- Diagnostics performed on 2630:16 fault code, with no trouble found ([2630:16 Diagnostics](#))

Please include the iKNOW document #(IK2200136) when opening a case file.

SYMPTOM

DTC/Light	Description
SPN 2630 FMI 16	CAC OT Undercooling

Hide Details

Feedback Information

Viewed: 98
 Helpful: 0
 Not Helpful: 0

No Feedback Found